# TOF AGRICULTURE ENTOF AGRICULT

## **BUREAU OF ANIMAL INDUSTRY**

# GENERAL PROCEDURES

Document Name:

# CALIBRATION OF EQUIPMENT

GP BAI-21

Rev. No.: 01 November 8, 2017

Page: 1/2

## 1.0 Objectives

- To ensure that measuring equipment are adjusted and calibrated against measurement standards traceable to international measurement standards.
- · To develop the calibration plan for all measuring and monitoring equipment

## 2.0 Scope

 This procedure covers all activities pertaining to the calibration of all measuring equipment and monitoring of actions taken.

### 3.0 Definition of Terms

CSP – refers to Calibration Service Provider

#### 4.0 Records

- Equipment Folder (Daily PM checklist, PM Checklist, Breakdown Report, PM Report/Calibration Certificate, Operation's Manual)
- R-BAI-11 Calibration Report File

### 5.0 References

#### 6.0 Process Flow

PROCESS	RESPONSIBILITY	DETAILS
Check/Review Calibration Plan	SH/UH/Analyst/ Specialist	SSC/USC to oversee schedule base on the PL- BAI 04 Calibration Plan
Prepare request for Calibration	SSC/USC	<ul> <li>Requests shall be done ahead of time prior to the scheduled date of calibration to give ample time for processing.</li> <li>Service Provider should be PAB accredited</li> </ul>
Perform Calibration  A	SSC/USC  Concerned Service  Provider	Inform EC

# OF AGRICULTURE RE

# **BUREAU OF ANIMAL INDUSTRY**

# **GENERAL PROCEDURES**


Document Name:

# CALIBRATION OF EQUIPMENT

GP BAI-21

Rev. No.: 01 November 8, 2017

Page: 2/2



Reviewed by:	Approved by:
ENGRAEDNCIO VENTOCILLO	RONNIE D. DOMINGO, DVM MSc
Equipment Custodian	Top Management